

European Commission | Product Safety Business Alert Gateway

Submission number 2018_1262

Case ID **2018/182/BE**

1 | Countries concerned

Countries concerned* Finland France Poland United


Kingdom Norway Belgium Italy Austria Denmark The

Netherlands Germany Greece Spain Sweden

2 | Producer/Distributor submitting notification

The producer/distributor* Is the Notifier

Sub-category



Astrid Lie OLSEN 20/09/2018 Page 1

Marine Engine

Trademark* MerCruiser

Model name 4.5, 6.2 8.2

Bar code

Total number of products held 482

Custom code

Country of origin* United States

Brief description* Stern drive Marine engine

Detailed description No file(s) attached

Photo - frontright3_4_png__475x600_q85_autocrop_size_canvas_subsampling-

2_upscale.jpg

4 | Risk assessment of the notifier

Description*

Mercury MerCruiser has observed contamination in certain powerassisted steering pumps and reservoirs on engines within thelisted serial number ranges. Pumps and related components on engines within the affected serial number range must be inspected and replaced, if necessary, with new components of an improved design that provide a better pump and pulley. Continued use of the pump could lead to overheating or in extreme circumstances, fire.

Record of accidents

Level of risk*

Report document

- smc18-05.pdf
- Risk Nomograph MerCruiser Power Steering Pump Overheat 08.16.18.xls

om end users

5 | Corrective actions already taken or planned

Please specify

Scope of the astions*

Duration of the astions*

Results of the actions

Reput.

Company taking action

Mercan

Additional information

6 | Company(ies) in the supply chain which hold affected products

Details of the COMPANY (IES) - List with contact persons.pdf

